

Change of PID values for services on Thor 5, Transponder C01.

As the services on Thor 5, transponder C01, will be moved to a new hardware platform, all services will be assigned new PID values. The changes are scheduled to take place 24th June at 10:00 UTC.

Please note that Service IDs will not be changed.

Transponder parameters (no changes):

Satellite: Thor 5
 Transponder: C09
 Downlink frequency: 11216 MHz
 Downlink polarisation: Vertical
 Symbol rate: 24,5 Msym/sec
 Forward Error Correction: 7/8
 DVB-S, QPSK

The changes will be:

TV4: Video PID: 1140 Audio PID: 3135 Teletext PID: 6042 PMT PID: 167 ECM PID: 7204	Kanal 11: Video PID: 1147 Audio PID: 3142 Teletext PID: 6049 PMT PID: 174 ECM PID: 7205
Sjuan: Video PID: 1145 Audio PID: 3140 Teletext PID: 6047 PMT PID: 172 ECM PID: 7206	TV4 Film: Video PID: 1142 Audio PID: 3137 Teletext PID: 6044 PMT PID: 169 ECM PID: 7209
TV4 Fakta: Video PID: 1141 Audio PID: 3136 Teletext PID: 6444 PMT PID: 168 ECM PID: 7212	TV12: Video PID: 1146 Audio PID: 3141 Teletext PID: 6126 PMT PID: 173 ECM PID: 7211
Kunskapskanalen: Video PID: 1272 Audio PID: 3268 Teletext PID: 6029 PMT PID: 301 ECM PID: 7210	SVTB/SVT24: Video PID: 1131 Audio PID: 3126 Teletext PID: 6026 PMT PID: 158 ECM PID: 7208
CANAL9 (D): Video PID: 1159 Audio PID: 3155 Teletext PID: 6036 PMT PID: 187 ECM PID: 7207	