

Change of PID values for services on Thor 5, Transponder C04.

As the services on Thor 5, transponder C04, will be moved to a new hardware platform, all services will be assigned new PID values. The changes are scheduled to take place 24th June at 11:00 UTC.

Please note that Service IDs will not be changed.

Transponder parameters (no changes):

Satellite: Thor 5
 Transponder: C04
 Downlink frequency: 11260 MHz
 Downlink polarisation: Horizontal
 Symbol rate: 24,5 Msym/sec
 Forward Error Correction: 7/8
 DVB-S, QPSK

The changes will be:

<p>C More Action: Video PID: 1083 Audio PID: 3078 Swedish Audio PID: 4054 Danish Audio PID: 4059 Norwegian Audio PID: 4060 Finnish Teletext PID: 6002 PMT PID: 110 ECM PID: 7213</p>	<p>C More Tennis: Video PID: 1090 Audio PID: 3085 Swedish Audio PID: 4073 Danish Audio PID: 4074 Norwegian Audio PID: 4075 Finnish Teletext PID: 6009 PMT PID: 117 ECM PID: 7214</p>
<p>C More Extreme: Video PID: 1088 Audio PID: 3083 PMT PID: 115 ECM PID: 7215</p>	<p>C More Kids: Video PID: 1078 Audio PID: 3313 Norwegian Audio PID: 4203 Danish Audio PID: 4213 Swedish Audio PID: 4215 Finnish Teletext PID: 6136 PMT PID: 291 ECM PID: 7217</p>
<p>SF Kanalen: Video PID: 1156 Audio PID: 3134 Swedish Audio PID: 4167 Danish Audio PID: 4166 Norwegian Audio PID: 4170 Finnish Teletext PID: 6071 PMT PID: 182 ECM PID: 7216</p>	<p>C More Hockey: Video PID: 1151 Audio PID: 3146 Teletext PID: 6420 PMT PID: 178 ECM PID: 7218</p>
<p>C More Live: Video PID: 1152 Audio PID: 3147 Norwegian Audio PID: 4151 Swedish Teletext PID: 6159 PMT PID: 179 ECM PID: 7219</p>	