

## Change of PID values for services on Thor 5, Transponder C05.

As the services on Thor 5, transponder C05, will be moved to a new hardware platform, all services will be assigned new PID values. The changes are scheduled to take place 24<sup>th</sup> June at 11:30 UTC.

**Please note that Service IDs will not be changed.**

Transponder parameters (no changes):

Satellite: Thor 5  
 Transponder: C05  
 Downlink frequency: 11278 MHz  
 Downlink polarisation: Vertical  
 Symbol rate: 24,5 Msym/sec  
 Forward Error Correction: 7/8  
 DVB-S, QPSK

**The changes will be:**

<b>C More First:</b> Video PID: 1086 Audio PID: 3081 Swedish Audio PID: 4067 Danish Audio PID: 4068 Norwegian Audio PID: 4069 Finnish Teletext PID: 6006 PMT PID: 113 ECM PID: 7220	<b>C More Series:</b> Video PID: 1084 Audio PID: 3079 Swedish Audio PID: 4061 Danish Audio PID: 4062 Norwegian Audio PID: 4063 Finnish Teletext PID: 6004 PMT PID: 111 ECM PID: 7224
<b>C More Sport:</b> Video PID: 1089 Audio PID: 3084 Teletext PID: 6008 PMT PID: 116 ECM PID: 7221	<b>C More Fotball:</b> Video PID: 1072 Audio PID: 3102 Teletext PID: 6051 PMT PID: 96 ECM PID: 7223
<b>C More Emotion:</b> Video PID: 1085 Audio PID: 3080 Swedish Audio PID: 4064 Danish Audio PID: 4065 Norwegian Audio PID: 4066 Finnish Teletext PID: 6005 PMT PID: 112 ECM PID: 7225	<b>C More Hits:</b> Video PID: 1087 Audio PID: 3082 Swedish Audio PID: 4070 Danish Audio PID: 4071 Norwegian Audio PID: 4072 Finnish Teletext PID: 6007 PMT PID: 114 ECM PID: 7226
<b>C More Fotboll:</b> Video PID: 1311 Audio PID: 3161 Teletext PID: 6422 PMT PID: 269 ECM PID: 7227	

Svein Bråten  
 Senior CSM – DTH Nordic  
 Broadcasting Systems - Technology Division  
 Telenor Satellite Broadcasting