

## Change of PID values for services on Thor 5, Transponder C02.

As the services on Thor 5, transponder C02, will be moved to a new hardware platform, all services will be assigned new PID values. The changes are scheduled to take place 13<sup>th</sup> January at 09:00 UTC.

**Please note that Service IDs will not be changed.**

Transponder parameters (no changes):

Satellite: Thor 5  
 Transponder: C02  
 Downlink frequency: 11229 MHz  
 Downlink polarisation: Horizontal  
 Symbol rate: 24,5 Msym/sec  
 Forward Error Correction: 7/8  
 DVB-S, QPSK

**The changes will be:**

<b>Animal Planet:</b> Video PID: 1079 Audio PID: 3074 Teletext PID: 6000 PMT PID: 106 ECM PID: 7240	<b>Discovery (D):</b> Video PID: 1482 Audio PID: 3535 Teletext PID: 6151 PMT PID: 677 ECM PID: 7241
<b>Discovery (D) syn:</b> Video PID: 1482 Audio PID: 4055 Teletext PID: 6151 PMT PID: 901 ECM PID: 7241	<b>Discovery (F):</b> Video PID: 1481 Audio PID: 3534 Teletext PID: 6149 PMT PID: 676 ECM PID: 7242
<b>Discovery (N):</b> Video PID: 1244 Audio PID: 3290 Norwegian Audio PID: 4093 English Teletext PID: 6010 PMT PID: 160 ECM PID: 7243	<b>Discovery (S):</b> Video PID: 1093 Audio PID: 3088 Teletext PID: 6010 PMT PID: 120 ECM PID: 7244
<b>Discovery (S) syn:</b> Video PID: 1093 Audio PID: 4050 Teletext PID: 6010 PMT PID: 900 ECM PID: 7244	<b>TLC Danmark:</b> Video PID: 1295 Audio PID: 3344 Teletext PID: 6028 PMT PID: 292 ECM PID: 7245
<b>TLC Danmark syn:</b> Video PID: 1295 Audio PID: 3345 Teletext PID: 6028 PMT PID: 339 ECM PID: 7245	<b>TLC Norge:</b> Video PID: 1013 Audio PID: 3013 PMT PID: 149 ECM PID: 7246
<b>TLC Sverige:</b> Video PID: 1293 Audio PID: 3318 PMT PID: 287 ECM PID: 7247	<b>BBC Lifestyle:</b> Video PID: 1187 Audio PID: 3183 Teletext PID: 6079 VBI PID: 6457 PMT PID: 215 ECM PID: 7248

**MTV:**

Video PID: 1163  
Audio PID: 3159  
Teletext PID: 6067  
PMT PID: 191  
ECM PID: 7249

Svein Bråten  
Senior CSM – DTH Nordic  
Broadcasting Systems - Technology Division  
Telenor Satellite Broadcasting