

## TV2 Denmark – Change of PID values

The TV2 Regional services will be moved to a new encoding platform 9<sup>th</sup> December 2013, and the PID values will be changed.

**Please note that the Service ID will not be changed.**

Transponder parameters (no changes):

Satellite: Thor 6  
 Transponder: A10  
 Downlink frequency: 10841 MHz  
 Downlink polarisation: Horizontal  
 Symbol rate: 24,5 Msym/sec  
 Forward Error Correction: 7/8  
 DVB-S, QPSK

**The changes will be:**

<b>TV2 / Lorry:</b> Video PID 1303 Audio PID 3299 PMT PID 384 TTXT PID 6368 ECM PID 7130	<b>TV2 / Nord:</b> Video PID 1336 Audio PID 3087 TTXT PID 6056 PMT PID 451 ECM PID 7129	<b>TV2 / Midt-Vest:</b> Video PID 1338 Audio PID 3096 TTXT PID 6370 PMT PID 453 ECM PID 7133
<b>TV2 / Østjylland:</b> Video PID 2088 Audio PID 3353 TTXT PID 6096 PMT PID 472 ECM PID 7131	<b>TV2 / Syd:</b> Video PID 1326 Audio PID 3337 TTXT PID 6388 PMT PID 441 ECM PID 7127	<b>TV2 / Fyn:</b> Video PID 2089 Audio PID 3354 TTXT PID 6405 PMT PID 473 ECM PID 7128
<b>TV2 / Øst:</b> Video PID 1320 Audio PID 3314 TTXT PID 6124 PMT PID 419 ECM PID 7091	<b>TV2 / Bornholm:</b> Video PID 1341 Audio PID 3107 TTXT PID 6129 PMT PID 455 ECM PID 7132	

The transition to the new encoding platform will take place within the scheduled planned work window, 09:00 – 10:00 UTC.