

Fornebu, 28th November 2016

C MORE GOLF HD – Change of FEC

The transponder that contains C MORE GOLF HD will change FEC (Forward Error Correction) from 3/4 to 2/3, 23rd January 2017 at 10:00 CET.

Old settings:

Satellite: Thor 7
Transponder: BSS40
Downlink frequency: 12476 MHz
Downlink polarisation: Horizontal
Symbol rate: 30,0 Msym/sec
FEC: 3/4
DVB-S2, 8PSK

New settings:

Satellite: Thor 7
Transponder: BSS40
Downlink frequency: 12476 MHz
Downlink polarisation: Horizontal
Symbol rate: 30,0 Msym/sec
FEC: **2/3**
DVB-S2, 8PSK

Service parameters:

“C MORE GOLF HD”, Conax Encrypted

Service ID:	7144
PMT PID:	474
Video PID:	1044
Audio PID 1:	3044 (swe)
Audio PID 2:	4002 (eng)
ECM PID:	7153

Svein Bråten
Senior CSM
Broadcasting Systems - Technology Division
Telenor Satellite